	Тур	L#	Hits	S arch Text	DB
1	IS&R	L2	1	("5857247").PN.	US- P PUB; USPAT
2	BRS	L3	78454	(squib or buckle or connector or latch) near6 (fire or firing or fired or unlatch or unlatching or unlatched or disconnect or disconnecting or disconnected or unbuckle or release or releasing or released)	PGPUB;
3	BRS	L4	62690	water with (activating or activate or activated)	US- PGPUB; USPAT; EPO; JPO; DERWE NT
4	BRS	L5	77	3 same 4	US- PGPUB; USPAT; EPO; JPO; DERWE NT
5	BRS	L6	17	5 and parachute	US- PGPUB; USPAT; EPO; JPO; DERWE NT

	Time Stamp	C mments	Error Definition	Erro rs
1	2005/01/20 18:24			
2	2005/01/20 18:30			
3	2005/01/20 18:31	·		
4	2005/01/20 18:31			
5	2005/01/20 18:47			

	Туре	L#	Hits	Search Text	DB
6	BRS	L7	40518	battery and (probe or sensor or wire) and (capacitor or capacitive)	US- P PUB; USPAT; EPO; JPO; DERWE
7	BRS	L8	3	6 and 7	US- PGPUB; USPAT; EPO; JPO; DERWE
8	BRS	L9	1	8 and diode	US- PGPUB; USPAT; EPO; JPO; DERWE
9	IS&R	L10	3904	((340/618) or (340/620) or (340/604) or (340/573.1) or (73/290R)).CCLS.	US- PGPUB; USPAT
10	BRS	L11	6	10 and 3 and 4	US- PGPUB; USPAT; EPO; JPO; DERWE NT
11	IS&R	L12	375	(340/644).CCLS.	US- PGPUB; USPAT

	Tim Stamp	Comm nts	Error D finiti n	Erro rs
6	2005/01/20 18:42			
7	2005/01/20 19:44			
8	2005/01/20 18:43			
9	2005/01/20 18:47			,
10	2005/01/20 19:44			
11	2005/01/20 19:55			

	Туре	L#	Hit	Search Text	DBs
					US-
					P PUB;
					USPAT;
12	BRS	L13	0	12 and 5	EPO;
					JPO;
				·	DERWE
					NT
	:				US-
					PGPUB;
				·	USPAT;
13	BRS	RS L14	0	0 12 and 5	EPO;
					JPO;
				·	DERWE
					NT
		RS L15 240 244/151B		240 244/151B	US-
					PGPUB;
					USPAT;
14	BRS		240 244/151B		EPO;
				JPO;	
				DERWE	
					NT
	IS&R	&R L16		US-	
15			117	117 (244/151B).CCLS.	PGPUB;
					USPAT
					US-
					PGPUB;
					USPAT;
16	BRS	L17 3 10	16 and 5	EPO;	
					JPO;
	,				DERWE
					NT

	Tim Stamp	Comm nt	Error Definiti n	Erro
12	2005/01/20 19:55		·	
13	2005/01/20 19:55			
14	2005/01/20 20:02			
15	2005/01/20 20:02			
16	2005/01/20 20:07			